

Report ID: 26,420,741 Version: 1 14 Nov 2024 Created:

Make:	Volkswagen	Model:	Tiguan	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	QWA39	<b>Reg Expiry:</b>	16 Oct 2025	Engine			
WoF Expiry:	17 Oct 2025	Odometer:	102,433 Kms	Good No:	26420741	Oil level	~		
VIN:	WVGZZZ5NZJW87966	Next Service:	105800	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	V		
						Performance	V		
Key:	SPSC S	-0	SD S		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC 6/6			ZIN	BIL SC	Operation	~		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent					741L	CV joints	~		
* = decals	sc 9/6			-NL	ETT SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC SC SC SC						Performance	~		
		Note: son	e defects & blemishes	may not be disr	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftyre	 (ک <sup>ر</sup>
						Right front		5	mm
						Left rear			
								5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
All wheel dr	-	ince inspectio	<u>eominents</u>			Suspension			
	ive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
Δυργορο						Electrical / Accessories			
Seats	Weldge					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
						Window winder FR	~		
General C	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Uriah Pepene Date: 14 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....