

Report ID: 26,421,218 Version: 1 20 Nov 2024 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Sedan | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|-------------------|----------------------|--|------|------------|----------|
| Year: | 2018 | Registration: | LWL511 | Reg Expiry: | 20 Mar 2025 | Engine | | | <u> </u> |
| WoF Expiry: | | Odometer: | 66,933 Kms | Good No: | 26421218 | Oil level | ~ | | |
| VIN: | W0VZS6EC1J1143158 | | | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | ~ · · · | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STE | A CO | | | X | Transmission | • | | |
| D = dent | SCWD | | | 1n- | | Operation | ~ | | |
| R = rust | | | | 10 | JHIN | Noise | ~ | | |
| PT = paint defe C = crack | ect III | | | + | w | Clutch | V | | ~ |
| P = pin dent | Ho | KI | | - | | CV joints | | | |
| * = decals | MIR | | | | ANR - | · · | ~ | | |
| SC = stone chi | ps US | VA | | 10 | | Wheel bearings | ~ | | |
| W = significant | t scuffs | - | | SUF | | Brakes | | | <u> </u> |
| | | Nataron | ne defects & blemishes | | | Performance Hand Brake | ~ | | <u> </u> |
| Body Insp | pection Comments | Note: som | ie delects & blemisnes | s may not be disp | hayed in the diagram | | | <i>c</i> . | Ļ |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 5. | | mm |
| | | | | | | Right front | 5. | | mm |
| | | | | | | Left rear | 3. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 510 | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | |
| | inage & onder bor | metinspectic | <u>on comments</u> | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | 1 |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Average | | | | | | Electrical / Accessories | , | | T |
| Seats | Avelage | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | <u> </u> |
| Dashboa | Average | | | | | Wipers (front & rear) | ~ | | <u> </u> |
| | | | | | | Window winder FL | ~ | | <u> </u> |
| Carriel | | | | | | Window winder FR | ~ | | <u> </u> |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | <u> </u> |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | <u> </u> |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry Central locking | | | | | | | ~ | | |
| | mina Masharian | T: | Chain | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected | d by: Greg Morgan | | | | | Date: 13 Nov 20 | 24 | | |

I have read and understood this condition guide.

Name:

Signature: