

|                                |  |                                |
|--------------------------------|--|--------------------------------|
| <b>Make:</b> Mitsubishi        | <b>Model:</b> Triton                     | <b>Body Style:</b> Utility     |
| <b>Year:</b> 2015              | <b>Registration:</b> JJG583              | <b>Reg Expiry:</b> 28 Sep 2025 |
| <b>WoF Expiry:</b> 05 Nov 2024 | <b>Odometer:</b> 212,177 Kms             | <b>Good No:</b> 26421738       |
| <b>VIN:</b> MMAJYKL10GH00632   | <b>Next Service:</b> 20/5/25 or 220023km | <b>Service History:</b> Yes    |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

**Body Inspection Comments**

Drivers side front wheel arch trim broken.  
RH side , side step bent up.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Surface corrosion underneath .

**Interior Comments**

|           |                                  |
|-----------|----------------------------------|
| Seats     | good besides drives seat ripped. |
| Carpets   | Good                             |
| Panels    | Good                             |
| Dashboard | Good                             |

**General Comments**

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

|   | Pass | Fail | N/A |
|---|------|------|-----|
| <b>Engine</b>                                       |      |      |     |
| Oil level   | ✓    |      |     |
| Smoke & fumes                                       | ✓    |      |     |
| Performance   | ✓    |      |     |
| Noise   | ✓    |      |     |
| <b>Cooling System</b>                               |      |      |     |
| Coolant condition                                   | ✓    |      |     |
| Performance   | ✓    |      |     |
| Radiator / Hoses (visual)                           | ✓    |      |     |
| <b>Transmission</b>                                 |      |      |     |
| Operation   | ✓    |      |     |
| Noise   | ✓    |      |     |
| Clutch  |      |      | ✓   |
| CV joints   | ✓    |      |     |
| Wheel bearings                                      | ✓    |      |     |
| <b>Brakes</b>                                       |      |      |     |
| Performance   | ✓    |      |     |
| Hand Brake  | ✓    |      |     |
| <b>Tyres</b> (lowest observed tread depth of tyres) |      |      |     |
| Left front  | 6    | mm   |     |
| Right front   | 6    | mm   |     |
| Left rear   | 6    | mm   |     |
| Right rear  | 6    | mm   |     |
| Spare   | Yes  |      |     |
| <b>Suspension</b>                                   |      |      |     |
| Suspension performance                              | ✓    |      |     |
| Steering performance                                | ✓    |      |     |
| Shock absorbers                                     | ✓    |      |     |
| <b>Air Conditioning / Heater</b>                    |      |      |     |
| Operation   | ✓    |      |     |
| <b>Electrical / Accessories</b>                     |      |      |     |
| Head lights   | ✓    |      |     |
| Tail lights   | ✓    |      |     |
| Indicators  | ✓    |      |     |
| Dashboard warning lights                            | ✓    |      |     |
| Wipers (front & rear)                               | ✓    |      |     |
| Window winder FL                                    | ✓    |      |     |
| Window winder FR                                    | ✓    |      |     |
| Window winder RL                                    | ✓    |      |     |
| Window winder RR                                    | ✓    |      |     |
| Rear view mirrors                                   | ✓    |      |     |
| Radio (basic test only)                             | ✓    |      |     |
| CD (basic test only)                                | ✓    |      |     |
| Number of keys                                      | 2    |      |     |
| Central locking                                     | ✓    |      |     |
| Remote locking                                      | ✓    |      |     |
| Sat. Nav. (basic test only)                         |      |      | ✓   |
| Reversing camera                                    | ✓    |      |     |

Inspected by: Aaron Johnson Date: 14 Nov 2024

I have read and understood this condition guide. Name: ..... Signature: .....