

Report ID: 26,421,786 Version: 2 Created: 14 Nov 2024

Make:	Mitsubishi	Model:	Triton	Body Style:	l Itility		Pass	Fail	N/A
Year:	2013		HDY666		Utility 25 Nov 2025	Engine	r ass	rall	
WoF Expiry:		Odometer:	HDY666 256,200 Kms	Reg Expiry: Good No:	25 NOV 2025 26421786	Oil level	~		
VIN:	MMAJNKB40ED00622					Smoke & fumes			
VIIN.	WIWIAJINKD40ED00022	Next Service.	4///25/01 205/2/KIII	Service mistor	y: No	l	~		
	port is not a warranty					Performance	~		
	a guide only. Conside sting undertaken. The					Noise	~		
	ical inspection prior to					Cooling System		1	T
						Coolant condition	~		
Key:	S D SC PT		S S	PT	S D C	Performance	~		
S = scratch	R	(0)	<u>Ant</u>	10/5	~	Radiator / Hoses (visual)	~		
D = dent	Alt				All	Transmission	1		1
R = rust	sw 96			10		Operation	~		
PT = paint def	ect			$  \rangle$		Noise	~		<u> </u>
C = crack	III				J∭	Clutch	~		<u> </u>
P = pin dent * = decals	ssc die			SI_	18445	CV joints	~		
SC = stone chi	ps U	Y C		10	SD SD	Wheel bearings	~		
W = significant scuffs						Brakes			
-	P SC W PT	$\sim$	S P S	PT	S	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Rear bumper pushed in.						Tyres (lowest observed tread depth of tyres)			2S)
RH canopy window won't shut.						Left front	1	0	mm
						Right front	1	0	mm
						Left rear		9	mm
Conditions During Body Inspection: Wet						Right rear		9	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Surface cor	rosion underneath.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior C	<u>omments</u>					Electrical / Accessories	1		1
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Average					Dashboard warning lights	~		1
	. Good					Wipers (front & rear)	~		1
Dashboa	ird Good					Window winder FL	~		1
	1					Window winder FR	~		1
<u>General</u> C	<u>Comments</u>					Window winder RL	~		1
Vehicle drove good.						Window winder RR	~		1
Ac not cold						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		1
						Number of keys	2	I	1
Road Conditions During Test Drive: Wet						Central locking	2 V		<u> </u>
nuau CON	uning res		Wet			Remote locking	v		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
	•								
Inspecte	d by: Aaron Johnson					Date: 14 Nov 20	)24		
Inspecter	d by: Aaron Johnson					Date: 14 Nov 20	)24		

I have read and understood this condition guide.

Name: .....

Signature: .....