

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends

Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Coolant condition V Performance W Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S SD Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs W Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front 7 mm **Right front** 7 mm Left rear 6.0 mm **Right rear** 6.0 mm Conditions During Body Inspection: Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats V Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL 1 Window winder RR V Rear view mirrors 1 Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera ~

Inspected by: Kilipati Mae

15 Nov 2024 Date:

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,423,840 Version: 3 Created: 04 Dec 2024

Pass

~

V

V

~

Engine

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A