

Report ID: 26,423,926 Version: 1 29 Nov 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2008	Registration:	ESL962	Reg Expiry:	30 Nov 2024	Engine			
WoF Expiry:	29 Jul 2025	Odometer:	275,965 Kms	Good No:	26423926	Oil level	~		
VIN:	MMBJNKA508D06986	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		<i>.</i>			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SDRSC	-0	SDRSC SDRSC		S R SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- Alt			The		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+	S R SC	Clutch	~		
P = pin dent	Ho	KI			JUII ——	CV joints	~		
* = decals	SRSC PR			AL-	SD SC	· ·			~
SC = stone chips						Wheel bearings			
W = significant scuffs S R SC S D SC S S D R SC						Brakes			
		Nata				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<u> </u>	Ļ
No key for canopy side windows.						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	-	mm
						Right front	4.	0	mm
						Left rear	3.	0	mm
Conditions During Body Inspection: Wet						Right rear	3.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	marks					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	scratches i	marks				Dashboard warning lights	~		
	scratches					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Driver door handle key hole covered over.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 211,883						Reversing camera			~
Inspected by: Gary Adams Date: 15 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....