

Basic Vehicle Condition Guide

Report ID: 26,424,231


Version:

Created: 28 Nov 2024

Make: Model: Mazda CX-5 **Body Style:** SUV Year: 2020 Registration: NBF170 Reg Expiry: 09 Dec 2024 WoF Expiry: **Odometer:** 27 Nov 2025 49,180 Kms **Good No:** 26424231 VIN: JM0KF2W7A00408198 Next Service: 57,700 km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chip - has been repaired with cert inside car.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

X1 key not working may not be for this vehicle lights work on key but won't lock or open.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

27 Nov 2024 Inspected by: Eleoit Kumar Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|----------|
| Engine | | | 1 |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | 1 | | |
| Operation | ~ | | |
| Noise | V | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | .0 | mm |
| Right front | 7.0 | | mm |
| Left rear | 4.0 | | mm |
| Right rear | | .0 | mm |
| Spare | Yes | | |
| Suspension | | 103 | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | <i>'</i> | | |
| Air Conditioning / Heater | • | | |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | | | |
| Indicators | V | | |
| Dashboard warning lights | 1/ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | | | |
| Window winder RL | ~ | | |
| | ~ | | |
| Window winder RR | V | | |
| Rear view mirrors | V | | |
| Radio (basic test only) | - | | <u> </u> |
| CD (basic test only) | <u> </u> | | ~ |
| Number of keys | 2 | | 1 |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ' | | |

Signature: