

Basic Vehicle Condition Guide

Report ID: 26,424,967


Version: 4

Created: 12 Dec 2024

Make: Model: Mitsubishi Pajero **Body Style:** SUV Year: 2005 Registration: CUW605 Reg Expiry: 11 Apr 2025 **Odometer:** WoF Expiry: 17 Nov 2024 404,693 Kms **Good No:** 26424967 VIN: JMFLYV78W5J003722 Next Service: 410000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Headlights dull/sunroof rusty/rust spots under paint

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd/front bumper support damage/steering rack leak/engine oil leak/minor underbody surface rust

| <u>Interior Comments</u> | | | |
|--------------------------|---------------------------|--|--|
| Seats | drivers bottom pad ripped | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Intermittent miss further investigation needed

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Uriah Pepene Date: 08 Dec 2024

Name:

| | Pass | Fail | N/A |
|------------------------------|----------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | | ~ | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | \(\sigma \) | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | V | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | depth | of tyre | es) |
| Left front | 8 | .0 | mm |
| Right front | 8 | .0 | mm |
| Left rear | 8.0 | | mm |
| Right rear | 8.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | V V | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | V V V V V V | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | / | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | - | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | |

Signature: