

Report ID: 26,425,720 5 Version: 21 Dec 2024 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	Wagon		Pass	Fail	N/A
Year:	2016	Registration:	MYE171	Reg Expiry:	05 Jul 2025	Engine			<u> </u>
WoF Expiry:	06 Dec 2025	Odometer:	83,382 Kms	Good No:	26425720	Oil level	~		
VIN:	KL3CA26U9GB517941	Next Service:	93000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	narge.	Coolant condition	~		
	S SC		P SC S P SC		S SC	Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			10	S SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				The second secon	SC	Clutch			~
P = pin dent	s sc				74Hb	CV joints	~		
* = decals		10		10	S SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
i significari	S SC S		S SC S SC		S SC	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
					Left front	3.2 mm			
						Right front	3.8 mm		mm
						Left rear	4.9 mm		mm
Conditions During Body Inspection: Wet						Right rear	5.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	minor stai	ns,wear,minor st	ains ,			Head lights	~		
Carpote						Tail lights	~		
Carpets	wear,minc	or stains ,				Indicators	~		
Panels	Good					Dashboard warning lights	2		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Drives okay	,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	2		
Engine Timing Mechanisms Timing Chain						Remote locking	۲		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 15 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....