

Basic Vehicle Condition Guide

Report ID: 26,425,847

Pass

~

1

/

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 14 Nov 2024


Fail

N/A

Make: Toyota Model: Hiace **Body Style:** Van Year: 2011 Registration: FQC220 **Reg Expiry:** 16 Dec 2024 WoF Expiry: **Odometer:** 28 Sep 2025 175,583 Kms **Good No:** 26425847 VIN: JTFHT02P705005968 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front lower cross member surface Rust.

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Good	

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Chris Buckley

Evidence of Cam Belt Replacement: Yes Kms: 150,861

Name:

Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch J CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 3.0 Right front 4.0 mm Left rear 7.0 mm Right rear 7.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR 1 Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

14 Nov 2024

Signature:

Date:

I have read and	understood this	condition guide.