

Report ID: 26,427,083 Version: 1 19 Nov 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility	[	Pass	Fail N/A
Year:	2015	<b>Registration:</b>	LKY679	Reg Expiry:	28 Mar 2025	Engine		1
WoF Expiry:	16 May 2025	Odometer:	201,398 Kms	Good No:	26427083	Oil level	~	
VIN:	, MMU148MK0FH62317	Next Service:	210000	Service Histor	V: No	Smoke & fumes	~	
						Performance	~	
	port is not a warranty		6	- Dauta have a st		Noise	· ·	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System		
a full mechan	ical inspection prior to	purchase and th	his can be arranged	for an additional o	harge.	Coolant condition	~	
						Performance	~	
Key:	sc	w m	S SC S P SC		N SSC	Radiator / Hoses (visual)	~	
S = scratch	STE	A CO			T	Transmission	•	
D = dent	scw 6/6				S SC W	Operation	~	
R = rust				10	JHIH	Noise	~	
PT = paint defe C = crack	ect III			+	S SC	Clutch	~	
P = pin dent	Ho							~
* = decals	SPSC DC				BIR SDSCW	CV joints	~	
SC = stone chips						Wheel bearings	~	
W = significant scuffs S SC SC W S P SC						Brakes	<u>г.</u> г	
						Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	
					Tyres (lowest observed tread depth of tyres)			
						Left front	4	mm
						Right front	5.8	mm
						Left rear	4.3	mm
Conditions During Body Inspection: Wet						Right rear	4 mm	
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension		
No underbody inspection 4x4 untested						Suspension performance	~	
4x4 unleste	:u					Steering performance	~	
						Shock absorbers	~	
						Air Conditioning / Heater		
						Operation 🖌		
Interior Comments						Electrical / Accessories		
Seats	wear, torn	drivers seat side				Head lights	~	
	Average					Tail lights	~	
Carpets	/ Telage					Indicators	~	
Panels	scratches,	wear				Dashboard warning lights	~	
	worrenet	eering wheel and	d gear knob			Wipers (front & rear)	~	
Dashboa	rd	cering wheel and	ש שכמו גווטט			Window winder FL	~	
	1				I	Window winder FR	~	
General Comments						Window winder RL	~	
						Window winder RR	~	
						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)		~
						Number of keys	1	
						Central locking	· ·	
Road Conditions During Test Drive: Wet						Remote locking	~	
Engine Tir	ming Mechanism:	Cambelt	t					
Evidence of Cam Belt Replacement: Yes Kms: 201,399						Sat. Nav. (basic test only)		~
				20		Reversing camera	~	
Inspected by: Melissa Wilson Date: 19 Nov 2024								

I have read and understood this condition guide.

Name: .....

Signature: .....