

Basic Vehicle Condition Guide

Report ID: 26,427,335


Version: 1

Created: 26 Nov 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2019 Registration: MBY577 Reg Expiry: 10 Jul 2025 **Good No:** WoF Expiry: **Odometer:** 05 May 2025 174,611 Kms 26427335 VIN: MMU148LK0KH65215 Next Service: 15/7/25 or 180000km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

s Kms: 148,384

Inspected by: Aaron Johnson Date: 26 Nov 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	✓ ✓		
Radiator / Hoses (visual)	/		
Transmission			•
Operation	~		
Noise	/		
Clutch			~
CV joints	~		
Wheel bearings	/		
Brakes			
Performance	~		
Hand Brake	/		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	ç)	mm
Right front	9		mm
Left rear	9		mm
Right rear	9		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Indicators Dashboard warning lights	ン ン ン		
	\(\times \)		
Dashboard warning lights	V V V		
Dashboard warning lights Wipers (front & rear)	> >		
Dashboard warning lights Wipers (front & rear) Window winder FL	> >		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	\(\times \) \(\t		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL	> >		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	\(\times \) \(\t		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	V V V V		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	V V V V V		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V V		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	VVVVVZ		
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	\(\times \) \(\t		

Signature: