

Report ID: 26,427,716 2 Version: 12 Dec 2024 Created:

| Make: | Toyota | Model: | Vanguard | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------------------------|----------------------|--|--------|------|-----|
| Year: | 2007 | Registration: | NJH880 | Reg Expiry: | 16 May 2025 | Engine | | | L |
| WoF Expiry: | 05 May 2025 | Odometer: | 166,377 Kms | Good No: | 26427716 | Oil level | ~ | | |
| VIN: | 7AT0H65BX20137774 | Next Service: | 176328 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Darts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | his can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | SCW | | | | SC | Performance | ~ | | |
| Key: | | -0 | S SC S SC | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | L |
| D = dent R = rust | SSC 615 | | | TIS | S SC | Operation | ~ | | |
| PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | | | ~ |
| P = pin dent | 110 | | | | 게 | CV joints | ~ | | |
| * = decals | s sc gle | | | -No- | S PT SC | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significan | t scuffs S SC | | S SC S SC | | S SC | Performance | ~ | | |
| Body Incr | pection Commonts | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Headlights dull/ | | | | | | Left front | 8.0 mm | | |
| | | | | | | Right front | 8 | .0 | mm |
| | | | | | | Left rear | 6 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.0 mm | | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| All wheel drive/front ball joints grease coming out/rear trail arm bushes cracked/ | | | | | | Suspension performance | ~ | | |
| An wheel u | nve/none ban joints gre | ase coming out/ | | TUCKCU/ | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | scratch ma | arks | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ard Average | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry Central locking | | | | | | | ~ | | |
| Remote loc | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | |
| Inspected by: Uriah Pepene Date: 02 Dec 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: