


| | | |
|--------------------------------|------------------------------|--------------------------------|
| Make: Holden | Model: Astra | Body Style: Hatchback |
| Year: 2018 | Registration: LFE925 | Reg Expiry: 15 Dec 2024 |
| WoF Expiry: 27 Nov 2025 | Odometer: 102,752 Kms | Good No: 26428074 |
| VIN: W0LBF6EH7HG17330 | Next Service: 113,000 | Service History: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments

| | |
|-----------|------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|-----------------------------------------------------|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 5.2 | mm | |
| Right front | 5.7 | mm | |
| Left rear | 4.9 | mm | |
| Right rear | 3.7 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | ✓ | | |
| Reversing camera | ✓ | | |

Inspected by: Hoani Saunders Date: 15 Nov 2024

I have read and understood this condition guide. Name: Signature: