

Basic Vehicle Condition Guide

Report ID: 26,428,832


Version: 2

Created: 19 Nov 2024

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2018 Registration: LEU261 Reg Expiry: 19 May 2025 WoF Expiry: **Odometer: Good No:** 03 Dec 2025 69,713 Kms 26428832 VIN: KL3CA26U9JB024142 Next Service: 76000 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor windscreen chips.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Right low beam not working.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Chris McQuade 19 Nov 2024 Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l denth	of tyre)
Left front		.0	mm
Right front		.0	mm
Left rear	2.8		mm
Right rear	3.0		mm
Spare	,	Yes	
Suspension		103	
Suspension performance	V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	_		
Operation	·		
Electrical / Accessories			
Head lights			
Tail lights			
Indicators	<i>'</i>		
Dashboard warning lights	V		
Wipers (front & rear)			
Window winder FL	V		
Window winder FR Window winder FR	V		
Window winder FK Window winder RL	V		
	V		
Window winder RR	V		
Rear view mirrors	-		
Radio (basic test only)	-		
CD (basic test only)			•
Number of keys	2		
Central locking	· •		
Remote locking	~		
Remote locking Sat. Nav. (basic test only) Reversing camera	<i>'</i>		~

I have read and understood this condition guide.

Name:

Signature: