

## **Basic Vehicle Condition Guide**

Report ID: 26,429,150

**Pass** 

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 17 Nov 2024

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

5

6

1

/

/

1

1

1


2

Yes

Make: Model: Volkswagen Polo **Body Style:** Hatchback Year: 2017 Registration: KHM798 **Reg Expiry:** 24 Jan 2025 WoF Expiry: **Odometer:** 13 Aug 2025 92,745 Kms **Good No:** 26429150 VIN: WVWZZZ6RZGU08371 **Next Service:** 97000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Underbody oxidation

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

## **General Comments**

One key fob not working

			-			1		
	Sat.	Nav. (basic test only)			~			
Kms:	Reve	ersing camera	~					
Date: 17 Nov 2024					l			
Name:	Signature:				•			

Road Conditions During Test Drive: Dry	Central locking	~		
-	Remote locking	V		
Engine Timing Mechanism: Cambelt		Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: No	Kms:	Reversing camera	~	
Inspected by: Kilipati Mae		Date: 17 Nov 20	24	
have read and understood this condition guide.	Name:	Signature:		