

Report ID: 26,429,892 3 Version: 12 Dec 2024 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	Registration:	MZK327	Reg Expiry:	24 Jan 2025	Engine		-	<u> </u>
WoF Expiry:	14 Oct 2025	Odometer:	104,145 Kms	Good No:	26429892	Oil level	~		
VIN:	7AT0DH78X20150023	Next Service:	114,150 Kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		c 1 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	sc	-0	D SC S SC		Р	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Transmission	•		
D = dent	s sc			The	EID S	Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				+	D SC	Clutch	•		~
P = pin dent						CV joints	~		
* = decals	s sc pp			AL.	SPT SC	Wheel bearings	~		
SC = stone chips							Brakes		
W = significant scuffs SC S SC S P SD SD						Performance	~		1
		Note: com	ne defects & blemishes			Hand Brake	~		
Body Insp	pection Comments	1016.301	le delects & blemisnes	s may not be disp	layed in the diagram		•	ofture	
						Tyres (lowest observed tread depth of tyres) Left front 1.5 mm			
									mm
						Right front	2.		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meenspeede	<u>Comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
						Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	Ird Average s	teering wheel w	orn			Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concret	Commonts					Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		Ļ
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine	ming Machaniana	T:	Cho:n			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Troy Smith					Date: 03 Dec 20	24		
	~~ <i>,</i>					Dute. 00 Det 20			

I have read and understood this condition guide.

Name:

Signature: