

Report ID: 26,431,535 Version: 1 27 Nov 2024 Created:

Make:	LDV	Model:	G10	Body Style:	Van		Pass	Fail	N/A
Year:	2018	Registration:	LJE618	Reg Expiry:	06 May 2025	Engine			
WoF Expiry:	15 Oct 2025	Odometer:	160,563 Kms	Good No:	26431535	Oil level	~		
VIN:	LSKG4GL17HA104159	Next Service:	due now	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for and milaana	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S R PT SC	-0	S R PT * SC S R PT *	<u>-</u>	S R PT * SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT SC			The	S PT SC	Operation	~		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	SRPTSC 916			AL.	SDPT*	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S R SC S PT * PT *						Performance	~		
		Note: som		may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftyre))
Lower bumper trim loose. Stone chips in front screen									
						Right front			mm
						Left rear	0		mm
									mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments							Spare Yes		
	inage a onder bor	meemspeede	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
marks rear's damaged						Electrical / Accessories			
Seats	marks, rea	r 5 dumugeu				Head lights	~		
Carpets	Average					Tail lights	~		
	coratchos	scuffs marks				Indicators		~	
Panels	scratches					Dashboard warning lights	~		
Dashboa	rd scratches,	speedometer cra	acked			Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General Comments Lh mirror indicator nw.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
			2 1 • .			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Gary Adams Date: 19 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: