

Report ID: 26,431,779 Version: 1 30 Nov 2024 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2007	Registration:	QUZ873	Reg Expiry:	10 Nov 2024	Engine		-	
WoF Expiry:	05 Mar 2025	Odometer:	286,783 Kms	Good No:	26431779	Oil level	~		
VIN:	KMHSH81WR7U24480			Service Histor		Smoke & fumes	~		
			2,0000			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition	~		
Key:	P SC		S D SC S SC		S SC	Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust						Operation	~		
PT = paint def	ect				S R SC	Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	s sc dk			SI_	18145	CV joints	~		
s s						Wheel bearings			
W = significant scuffs						Brakes			
	SC	\sim	P SC S P SC		S P SC	Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Front grille needs paint ,						Tyres (lowest observed tread depth of tyres)			
					Left front 3.7		.7	mm	
						Right front	4	.1	mm
						Left rear	3	.6	mm
Conditions During Body Inspection: Dry					Right rear	5.1 mm		mm	
						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories		~	
wear worn torn minor stains									
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Drives okay Fresh service						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•								•
Inspected by: Donovan Matara Date: 19 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: