

Basic Vehicle Condition Guide

Report ID: 26,431,910


Version: 3

Created: 10 Dec 2024

Make: Model: Foton Tunland **Body Style:** Utility Year: 2015 Registration: JML810 Reg Expiry: 07 Dec 2024 WoF Expiry: **Odometer:** 01 May 2025 138,152 Kms **Good No:** 26431910 VIN: LVAV2MBB8FJ045588 Next Service: No Sticker Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rust patch bottom of LH/F door , Rust around tailgate hinges, Structural rust near bonnet hinges

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive, Rust patches in behind rear bumper,

Interior Commo	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Reverse camera not working,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson 22 Nov 2024 Inspected by:

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>v</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation		~		
Noise		~		
Clutch	~			
CV joints			~	
Wheel bearings	~			
Brakes				
Performance		~		
Hand Brake		~		
Tyres (lowest observed tread depth of tyres)				
Left front	2	.0	mm	
Right front	4	.0	mm	
		.0	mm	
Right rear	2.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V			
Dashboard warning lights	~			
Wipers (front & rear)		~		
Window winder FL	~			
Window winder FR	~			
Window winder RL	\(\triangle \)			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	1		
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera		~		

Signature: