

Report ID: 26,433,155 Version: 6 Created: 27 Nov 2024

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	GUW126	Reg Expiry:	29 Oct 2025	Engine			<u> </u>
WoF Expiry:	03 Apr 2025	Odometer:	143,355 Kms	Good No:	26433155	Oil level	~		
VIN:	6G1PD6E57DL810560	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
			,		,	Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Darts have not been dismontiad as						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	SC S	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC PIP						Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S S S P S S						Performance	~		
						Hand Brake	~		
Body Inspection Comments							•	oftyre	
						Tyres (lowest observed tread depth of tyres)			mm
						Right front Left rear		.0	mm
								.0	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories	1		
Seats	Sindi np i	ranvers seat.				Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Guu					Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		<u> </u>
General Comments Oil leaks.						Window winder RL	~		<u> </u>
Cambelt due @ 150,000kms						Window winder RR	~		
						Rear view mirrors	~		ļ
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
Engine T	ming Machanism	Caraka	•			Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspecte	Inspected by: Lewis Dolamore Date: 20 Nov 2024								
I have read and understood this condition guide. Name:									