

## **Basic Vehicle Condition Guide**

Report ID: 26,434,862


Version: 1

Created: 22 Nov 2024

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2019 Registration: MGC933 Reg Expiry: 30 Oct 2024 **Odometer:** WoF Expiry: 16 May 2025 76,977 Kms **Good No:** 26434862 VIN: MPATFR85JJT005724 **Next Service:** 85,000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Front bumper impact damage

| Conditions During Body Inspection: | Dry |
|------------------------------------|-----|
|------------------------------------|-----|

**Under Carriage & Under Bonnet Inspection Comments** 

**RWD** 

| Interior Comments | 2    |
|-------------------|------|
| Seats             | Good |
| Carpets           | Good |
| Panels            | Good |
| Dashboard         | Good |

## **General Comments**

Stone chips on windshield, battery weak needs charging

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

22 Nov 2024 Inspected by: Allan Young Date:

Name: .....

|   | T _             | T    |          |
|---|-----------------|------|----------|
|   | Pass            | Fail | N/A      |
| Engine                                      |                 |      | ı        |
| Oil level                                   | ~               |      |          |
| Smoke & fumes                               | V V             |      |          |
| Performance                                 | ~               |      |          |
| Noise                                       | ~               |      |          |
| Cooling System                              | 1               |      | 1        |
| Coolant condition                           | \( \triangle \) |      |          |
| Performance                                 | ~               |      |          |
| Radiator / Hoses (visual)                   | ~               |      |          |
| Transmission                                |                 |      |          |
| Operation                                   | <i>'</i>        |      |          |
| Noise                                       | ~               |      |          |
| Clutch                                      |                 |      | ~        |
| CV joints                                   |                 |      | ~        |
| Wheel bearings                              | ~               |      |          |
| Brakes                                      |                 |      | I        |
| Performance                                 | ~               |      |          |
| Hand Brake                                  | · ·             |      |          |
| Tyres (lowest observed tread                |                 |      | _        |
| Left front                                  |                 | 9    | mm       |
| Right front                                 |                 | 9    | mm       |
| Left rear                                   |                 | 8    | mm       |
| Right rear                                  |                 | 8    | mm       |
| Spare                                       |                 | Yes  |          |
| Suspension                                  |                 |      | 1        |
| Suspension performance Steering performance | <i>v</i>        |      |          |
| Steering performance Shock absorbers        | -               |      |          |
|   | •               |      |          |
| Air Conditioning / Heater                   |                 |      |          |
| Operation  Electrical / Accessories         | <i>'</i>        |      |          |
| Head lights                                 |                 |      |          |
| Tail lights                                 |                 |      |          |
| Indicators                                  |                 |      |          |
| Dashboard warning lights                    |                 |      |          |
| Wipers (front & rear)                       | V<br>V<br>V     |      |          |
| Window winder FL                            | 1               |      |          |
| Window winder FR                            | \( \sigma \)    |      |          |
| Window winder RL                            |                 |      |          |
| Window winder RR                            |                 |      | 1/       |
| Rear view mirrors                           | ~               |      | <b> </b> |
| Radio (basic test only)                     |                 |      |          |
| CD (basic test only)                        | <i>'</i>        |      |          |
| Number of keys                              | _               |      |          |
| Central locking                             | 1               |      |          |
| Remote locking                              | .,              |      |          |
| Sat. Nav. (basic test only)                 |                 |      | .,       |
| Reversing camera                            | .,              |      |          |
| neversing calliera                          |                 |      |          |

Signature: .....