

Report ID: 26,436,373 Version: 1 22 Nov 2024 Created:

Signature:

Make:	Ford	Model:	Territory	Body Style:	SUV] [Pass	Fail	N/A
Year:	2012	Registration:	GPP163	Reg Expiry:	19 May 2025	Engine			
WoF Expiry:		Odometer:	297,638 Kms	Good No:	26436373	Oil level	~		
VIN:	6FPAAAJGATCK82346			Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty			-		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	s w	-0	SP SP		SP	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent							Operation 🖌		
R = rust PT = paint defect						Noise	~		
C = crack				+	SC	Clutch	-		~
P = pin dent						CV joints	~		
* = decals S D R P P P S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W S P S P W						Performance	~		
		Note: son			laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
AC not working on drivers side Right Rear window switch works in reverse						Tyres (lowest observed tread depth of tyres) Left front 6.1 mm			
Stone chips in windscreen							+	.1	mm mm
Hoodlining loose in front area						Right front Left rear	-	0.2	
						1	-	4.9 r	
Conditions During Body Inspection: Dry						Right rear	5.3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	inage a onder bor	ince inspectie	<u>eoninento</u>			Suspension performance			
							~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
Poor						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Poor					Tail lights	~		
	Poor					Indicators	~		
Panels						Dashboard warning lights			
Dashboa	rd Poor					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments Has head phone for overhead screen						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~ ~		
Engine Timing Mechanism: Cambelt Remote locking									
Evidence of Cam Belt Replacement: Yes Kms: 165,987						Sat. Nav. (basic test only)	1		~
	or cam beit neplac	cilicili. Y	C3	1113. [0	105,01	Reversing camera	~		
Inspected by: Lindsay Malpas Date: 21 Nov 2024									

I have read and understood this condition guide.

Name: