

Report ID: 26,437,298 Version: 1 21 Nov 2024 Created:

Make:	Toyota	Model:	Altezza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2001	Registration:		Reg Expiry:	10 Oct 2025	Engine	I	<u> </u>	1
WoF Expiry:		Odometer:	302,301 Kms	Good No:	26437298	Oil level	~		
VIN:	7AT0H639X10044883	Next Service:	309000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		+
	port is not a warranty		f	Dauta hava a at		Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	nical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
			[			Performance	~		+
Key:	SRSC	-0	S R P SC S PT SC		S R PT SC	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			
D = dent SC W D D PT W						Operation	~		1
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack				+	R SC	Clutch			~
P = pin dent					세비	CV joints	~		+
* = decals	R SC 916				ET SPT	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs D R PT SCI W S SC S D SC W D R PT SCI						Performance	~		T
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		+
	pection Comments			indy not be disp		Tyres (lowest observed treat	-	oftyre	
Boot door misaligned									
						Right front			mm mm
						Left rear	6		mm
			_						-
Conditions During Body Inspection: Dry						Right rear 4 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
					Suspension performance			1	
Rear differe							~		
						Steering performance Shock absorbers	~		+
							~		
						Air Conditioning / Heater			T
Interior Comments						Operation Electrical / Accessories	~		
Poor						Head lights			T
Seats							<b>v</b>		+
Carpets	Poor					Tail lights Indicators	レ レ		+
	Poor								+
Panels						Dashboard warning lights	<b>v</b>		+
Dashboa	rd Poor					Wipers (front & rear) Window winder FL	V 		+
						Window winder FL Window winder FR	V		+
General Comments						Window winder FR Window winder RL	V 		+
Partial service history receipts in glove compartment						Window winder RL Window winder RR	V 		+
	to cam belt replaceme					Rear view mirrors	<b>v</b>		+
							V 		+
						Radio (basic test only) CD (basic test only)	<b>v</b>		+
						Number of keys			
						Central locking	1		1
Road Conditions During Test Drive: Dry						<u> </u>	~		
Engine Timing Mechanism: Cambelt						Remote locking			V
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			<b>v</b>
		I'				Reversing camera			~
Inspecte	d by: Sione Mae					Date: 21 Nov 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....