

Report ID: 26,437,752 Version: 1 22 Nov 2024 Created:

Make:	BMW	Model:	3201	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	QBB465	Reg Expiry:	28 Jun 2024	Engine			L
WoF Expiry:	21 Oct 2025	Odometer:	54,255 Kms	Good No:	26437752	Oil level	~		
VIN:	WBAUS92040A861122	Next Service:	53,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			SC S		SC	Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			20	HI Is	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TTY .		Clutch			~
P = pin dent	s de				2416	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significan		\sim	SC S P		S	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	;	mm
						Right front	6	,	mm
						Left rear	6	,	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
					Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
RWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		
<u>General Comments</u> Fault codes.						Window winder RL	~		<u> </u>
Fault Coues						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Engine Ti	ming Mechanism	Timina (- Thain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Imraan Bryant Date: 22 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: