

Report ID: 26,438,012 3 Version: 12 Dec 2024 Created:

Signature: .....

Make:	Volvo	Model:	S60	Body Style:	Sedan	] [	Pass	Fail	N/A
Year:	2012	Registration:	GER998	Reg Expiry:	30 May 2025	Engine			
		Odometer:	143,689 Kms	Good No:	26438012	Oil level	~		
VIN:	YV1FS485BC2105718	Next Service:		Service Histor		Smoke & fumes	~		
	11115105502105710		onation		, 110	Performance	~		
	port is not a warranty		~ · · ·			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~	•	
Key:	S P SC	-0	S P SC S		s	Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			X	Transmission	V		
D = dent	SCSCW			11-1	BID SW	Operation		~	
R = rust				10		Noise	~	V	
PT = paint defe C = crack				+	S	Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	s sc qk				ENR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SP SP SP SP SP						Performance	~		1
		Note: son	ne defects & blemishe	s may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	Note: 3011	le delects & blemsne	s may not be disp	hayed in the diagram		-	ofture	) )
Headlights Faded						Tyres (lowest observed tread depth of tyres)			
Stone Chips Windscreen						Left front			mm
						Right front			mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear 5.5 mm			mm
Under Carriage & Under Bonnet Inspection Comments					Spare N/A				
		meemspeede	<u>Comments</u>			Suspension			
	nt Leak - Expected for A					Suspension performance	~		
Recommen	d Rear Left & Front Righ	nt Replace Tyre				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights		~	
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Running Ro	ough - Unknown Reasor	ning				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Tir	ming Mechanism:	Cambel	+			Remote locking	~		
Evidence of Cam Belt Replacement: Yes Kms: 98,949						Sat. Nav. (basic test only)			~
Lvidence	or carri bert nepide	ernent. Y	5	1113. 98	),747	Reversing camera			~
Inspected by: Samuel Weir Date: 09 Dec 2024									

I have read and understood this condition guide.

Name: .....