

Basic Vehicle Condition Guide

Report ID: 26,438,388


Version: 2

Created: 23 Nov 2024

Make: Model: Subaru ΧV **Body Style:** Hatchback Year: 2013 Registration: QDH695 Reg Expiry: 27 Sep 2025 WoF Expiry: **Odometer: Good No:** 20 Sep 2025 101,918 Kms 26438388 VIN: 7AT0GF1XX23046691 Next Service: 103,686 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dean Sinclair Date: 22 Nov 2024

Pass	Fail	N/A
~		
~		
~		
~		
•	•	
~		
~		
~		
•	•	•
~		
~		
		~
~		
~		
•		
~		
~		
depth	of tyre	es)
4	.5	mm
5	.0	mm
4.0		mm
5.0		mm
	N/A	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
2	•	
~		
•		
~		
~		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

I have read and understood this condition guide.

Name:

Signature: