

Report ID: 26,438,595 Version: 1 22 Nov 2024 Created:

Signature:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2015	Registration:	JMA17	Reg Expiry:	26 Nov 2025	Engine			
WoF Expiry:	20 Nov 2025	Odometer:	49,406 Kms	Good No:	26438595	Oil level	~		
VIN:	KMFWBX7KMFU76193	Next Service:	58,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged to	or an additional of	.narge.	Coolant condition	~		
			S D W P SC W		SCW	Performance	~		
Key:				500-	Jew	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sw			20	BUSDW	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				2416	CV joints			~
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	W		SPW SDW		S P W	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Rear bumper impact damage						Tyres (lowest observed tread depth of tyres)			es)
						Left front 7			mm
						Right front	8	3	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
RWD Engine leaking oil						Suspension performance	~		
Engine leak	ing oli					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Stone chips	on windshield					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Allan Young Date: 22 Nov 2024									

I have read and understood this condition guide.

Name: