

Report ID: 26,438,700 Version: 1 25 Nov 2024 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A	
Year:	2010	Registration:	FFQ526	Reg Expiry:	02 Feb 2025	Engine	1 433	i an		
WoF Expiry:		Odometer:	161,227 Kms	Good No:	26438700	Oil level	~			
VIN:	MM0UNY0E40084926			Service Histor		Smoke & fumes	~			
•	MIMOONT0240004920		171,173 Km		• • • • •	Performance	~			
	port is not a warranty					Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
		_				Performance	~			
Key:		-0	PT P SC			Radiator / Hoses (visual)	v v			
S = scratch						Transmission				
D = dent						Operation				
R = rust				10	JHIN	Noise	~ ~			
PT = paint def C = crack	ect M			+	R SC	Clutch	v v			
P = pin dent	Htc	KI			JUII ——	CV joints	v v			
* = decals	- MIK			AL-		Wheel bearings	-			
SC = stone chips						Wheel bearings				
W = significant scuffs										
		Nata				Performance	~			
Body Ins	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake		<u> </u>		
Bonnet guard peeling.						Tyres (lowest observed tread depth of tyres)				
Aerial bracket on bonnet. Rear deck bracket not bolted in.						Left front		5	mm	
Anchors in	tray rusty from top⊥	tom.				Right front		7	mm	
						Left rear		7	mm	
Conditions During Body Inspection: Dry									mm	
Under Carriage & Under Pennet Inspection Comments						Spare N/A				
Under Carriage & Under Bonnet Inspection Comments RWD. Surface rust underside.						Suspension		1	1	
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	1	1	1	
Interior Comments						Operation	~			
Interior Comments						Electrical / Accessories		1		
Seats	1001					Head lights	~			
Carpets	Average					Tail lights	~			
						Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	Average					Wipers (front & rear)	~			
						Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL			~	
X1 heater logo missing on dash. Radio damaged.						Window winder RR			~	
Fault codes B1318 batt voltage.						Rear view mirrors	~			
TTED DISIG	voitage.					Radio (basic test only)		~		
						CD (basic test only)		~		
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking			<	
с		<u> </u>				Remote locking			<	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~	
	Inspected by: Imraan Bryant Date: 25 Nov 2024									
Inspected by. Inflaan bryant Date: 25 NOV 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....