

Report ID: 26,439,419 Version: 2 05 Dec 2024 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2018	Registration:	LJZ852	Reg Expiry:	28 Sep 2025	Engine			L
WoF Expiry:	03 Dec 2025	Odometer:	126,949 Kms	Good No:	26439419	Oil level	~		
VIN:	KMFWBX7KLJU972537	Next Service:	136,000 Kms	Service Histor	y: Yes	Smoke & fumes	~		
			•			Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
	*					Performance	~		
Key:		-0	* SDR *		SDR*	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc w			715	HIV	Operation	~		
PT = paint defe		F I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					S D	Clutch	~		
P = pin dent	HID				7414	CV joints			~
* = decals	sc 916			-July		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant	D*		D R * P *		*	Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Front bumper two hook cover missing						Left front	3.4 mm		
						Right front	3.	7	mm
						Left rear	2.	7	mm
Conditions During Body Inspection: Dry						Right rear	3.4 mr		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Hoani Saunders					Date: 02 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: