

Basic Vehicle Condition Guide

Report ID: 26,439,426


Version: 1

Created: 02 Dec 2024

Make: Model: Mercedes-Benz **B-Class Body Style:** Hatchback Year: 2013 Registration: HBK613 Reg Expiry: 29 Sep 2025 WoF Expiry: **Odometer:** 27 Nov 2025 111,249 Kms **Good No:** 26439426 VIN: WDD2462422J179633 Next Service: 120,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

22 Nov 2024 Inspected by: Gary Adams Date:

Name:

| | Pass | Fail | N/A | | |
|--|--|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | VVV | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | \(\triangle \) | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 7 | .0 | mm | | |
| Right front | 7 | .0 | mm | | |
| Left rear | 5.0 | | mm | | |
| Right rear | 5.0 | | mm | | |
| Spare | | N/A | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | \(\times \) | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | \(\times \) \(\t | | | | |
| Window winder FR | • | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | • | | | | |
| Rear view mirrors | | | | | |
| Radio (basic test only) | • | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | - | | | | |
| Remote locking | - | | | | |
| Sat. Nav. (basic test only) | V | | | | |
| Reversing camera | ' | | | | |

Signature: