

Basic Vehicle Condition Guide

Report ID: 26,439,435


Version: 1

Created: 27 Nov 2024

Make: Model: ES300H Lexus **Body Style:** Sedan Year: 2014 Registration: HHL811 Reg Expiry: 25 Jul 2025 WoF Expiry: **Odometer: Good No:** 06 Dec 2025 148,924 Kms 26439435 VIN: JTHBW1GGX0205373(Next Service: 160200kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lindsay Malpas 22 Nov 2024 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	>		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	V V		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.4	mm
Right front	3	.7	mm
Left rear	4.3		mm
Right rear	5.2 r		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V V V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2	1	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		
1		1	

Signature: