

Basic Vehicle Condition Guide

Report ID: 26,440,365


Version: 1

Created: 22 Nov 2024

Make: Model: Honda Jazz **Body Style:** Hatchback Year: 2023 Registration: PSS156 Reg Expiry: 14 Feb 2025 WoF Expiry: **Odometer:** 02 Feb 2026 10,623 Kms **Good No:** 26440365 VIN: JHMGS4850NS200328 Next Service: 25,100km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| Interior Commo | <u>ents</u> |
|----------------|-------------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

22 Nov 2024 Inspected by: Rowan Fey Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|-----------------|----------|----------|--|
| Engine | • | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | \(\triangle \) | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 6 | 5 | mm | |
| Right front | 6 | | mm | |
| Left rear | 6 | | mm | |
| Right rear | 6 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | ı | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \(\tau \) | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | <u> </u> | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | / | |
| Reversing camera | _ | | Ť | |
| | L | | | |
| | | | | |

Signature: