

Report ID: 26,443,064 Version: 2 Created: 11 Dec 2024

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2004		CHD587	Reg Expiry:	50V 01 Jan 2025	Engine	1 035	i all	
WoF Expiry:		Odometer:		Good No:					<u> </u>
			259,991 Kms		26443064	Oil level	~		<u> </u>
VIN:	JF2BP9KLA5G017092	Next Service:	252,028	Service Histor	y: No	Smoke & fumes	~		<u> </u>
Note: This re	port is not a warranty					Performance	~		<u> </u>
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
	······		J		, see the second s	Coolant condition	~		
Kow	S R SC		SRPSC SD		S D R SC W	Performance	~		
Key: S = scratch		$\overline{(0)}$		5(O)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s sc w			10	SW.	Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					S R SC	Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals S C 9 9 S PT						Wheel bearings	~		
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs S R SC S R PT SC V S R C SC W S R SC						Performance	~		
		Note: con				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	of +	<u> </u>
Minor Stone Chips Windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front 4.5		.5	mm
						Right front	5	.0	mm
						Left rear	0.0		mm
Conditions During Body Inspection: Dry						Right rear	3	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			4
						Operation	~		
Interior Comments						Electrical / Accessories			.1
Seats	Average					Head lights		~	
						Tail lights	~	•	
Carpets	Average					Indicators	· ·		
Panels	Average					Dashboard warning lights	• •		-
Panels						Wipers (front & rear)	v v		
Dashboa	rd Average					-			
						Window winder FL	v		
Ganaral	omments					Window winder FR	~		
<u>General Comments</u> Central Locking - Rear Doors Operate						Window winder RL		~	<u> </u>
Front Windows Working						Window winder RR		~	<u> </u>
AC Belt Squeak						Rear view mirrors	~		
Right Headlight Dip - Need Replacing Cambelt Replaced Armstrong Christchurch 9/12/2019 @ 200,641						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking		~	
			•			Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 2(0,641	Reversing camera			~
								1	
Inspected by: Samuel Weir Date: 29 Nov 2024									
I have read	and understood th	is condition o	uide. Name:			Signature:			