

Report ID: 26,443,713 2 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	FDH467	Reg Expiry:	18 Sep 2025	Engine	1		1
WoF Expiry:	14 Oct 2025	Odometer:	167,089 Kms	Good No:	26443713	Oil level	~		
VIN:	JF1GH7KS59G034417	Next Service:	177068	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S SC S		S SC S SC		S SC	Performance	~		
Key:	330 3	-0	330 330	-01-	330	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S C S D SC						Operation	~		
PT = paint defe		FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIG				74114	CV joints	~		
* = decals	s sc gle				FID SSC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S SC S SC S SC S SC						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
								mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	ii ya (Suspension performance	~		
All wheel di	rive/					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Seats Average					Head lights	~		
						Tail lights	~		
Carpets	hole in flo	or mat				Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	l	I
Road Conditions During Test Drive: Dry						Central locking	- -		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Tir	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Yes Kms: 103,000						Reversing camera			~
Inspected by: Uriah Pepene Date: 04 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: