

Pass Fail N/A

Year:	2009	<b>Registration:</b>	EUE212	<b>Reg Expiry:</b>	01 Nov 2025	Engine			
WoF Expiry:	14 Jun 2025	Odometer:	135,396 Kms	Good No:	26443980	Oil level	~		
VIN:	JHMCU26809C208857	Next Service:	145,395kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
<b>N C T</b>						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and ti	lis can be arranged ic		inarge.	Coolant condition	~		
	S SC S		S P S P	S	S	Performance	~		
<b>Key:</b> S = scratch	1330 [[3	=(0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent R = rust S SC S						Transmission			
						Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TT	S SC	Clutch		~	
P = pin dent	ssc de				2416	CV joints	~		
SC = stone chips W = significant scuffs						Wheel bearings	~		
						Brakes			
in significant	SC S	C	S S		S	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
<u>,</u>						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0	mm	
						Right front	3.2	mm	
						Left rear	7.2	mm	
Conditions During Body Inspection: Dry						Right rear	7.2 mm		
		·				Spare	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comot	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jason Young Date: 27 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....