

Basic Vehicle Condition Guide

Report ID: 26,444,665

Pass

Version: 2

Created: 03 Dec 2024


Fail

N/A

Make: Volkswagen Model: Golf **Body Style:** Hatchback Year: 2008 Registration: MZS704 **Reg Expiry:** 05 May 2025 WoF Expiry: **Odometer:** 15 Aug 2025 103,161 Kms **Good No:** 26444665 VIN: WVWZZZ1KZ8U01338 Next Service: 122,000kms Service History: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Hood lining starting to fall down.		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Ye

Kms: 92,700

Engine Oil level Smoke & fumes ~ Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 3.0 Right front 3.0 mm Left rear 5.0 mm Right rear 5.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) 1 CD (basic test only) / Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

Signature:

Inspected by:	Lewis Dolamore	Date:	26 Nov 2024
---------------	----------------	-------	-------------

Name: