

Basic Vehicle Condition Guide

Report ID: 26,445,152


2 Version:

12 Dec 2024 Created:

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2021 Registration: NGT445 Reg Expiry: 28 Jan 2025 WoF Expiry: **Odometer: Good No:** 30 Jan 2025 93,718 Kms 26445152 VIN: MMAJLKL10MH008615 **Next Service:** 103000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Rip in drivers seat			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Kilipati Mae 02 Dec 2024 Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	l		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	9	.0	mm
Right front	9	.0	mm
Left rear	9	.0	mm
Right rear	9	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	<u> </u>		
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	\(\times \)		
Dashboard warning lights	<i>\sqrt{\sq}}}}}}}}}}}}}} \sqite\septionup\sign{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}} \sqrt{\sq}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}} \sqite\septintite\septionup\sint{\sintend{\sinq}}}}}}} \sqite\septitite{</i>		
Wipers (front & rear)			
Window winder FL	\(\triangle \)		
Window winder FR	~		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	~		
	•		
Radio (basic test only) CD (basic test only)			V
Number of keys	2		
Central locking	2 V		
Remote locking	•		
			.,
Sat. Nav. (basic test only)	~		-
Reversing camera			
Date: 02 Dec 20	24		

I have read and understood this condition guide.

Name:			