

Report ID: 26,445,650 Version: 2 26 Nov 2024 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:		Reg Expiry:	29 Mar 2025	Engine			
WoF Expiry:		Odometer:	68,678 Kms	Good No:	26445650	Oil level	~		
VIN:	JMFXTGF8WLZ021304			Service Histor		Smoke & fumes	~		
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		. 105	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
				_		Performance	~		
Key:		-0	SP S			Radiator / Hoses (visual)	~ ~		
S = scratch						Transmission			
D = dent	IS OF			1 - L	BID SD				<u> </u>
R = rust				10		Operation Noise			
PT = paint def C = crack	ect 1			+		Clutch	V		
P = pin dent	LHC								~
* = decals	SDSC PR			SI_		CV joints Wheel bearings	~		
SC = stone chips									I
W = significant scuffs W S S						Brakes			<u> </u>
		Natarcam				Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<i>C</i> .	Ļ
Left wing mirror cover scratched.						Tyres (lowest observed tread depth of tyres)			
Right wing mirror inner housing cracked.						Left front	5		mm
						Right front	4.		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
Under Comiene & Under Deservation Comments					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
All wheel d	rive.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central lockir							~		
		· · ·	•			Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Takaya Murayama Date: 26 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....