

Report ID: 26,447,141 5 Version: 12 Dec 2024 Created:

Signature:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2003	Registration:	QYB629	Reg Expiry:	02 Dec 2024	Engine			
WoF Expiry:	09 Dec 2025	Odometer:	344,548 Kms	Good No:	26447141	Oil level	~		
VIN:	MMBJNK6703D079379	Next Service:	354,534	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	oort is not a warranty a quide only Consid		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	r an additional o	narge.	Coolant condition	~		
	S SC		S D R SC S D PT		S D R W	Performance	~		
key:						Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	~		
P = pin dent						CV joints			~
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S D PT S D W S R P W						Performance	~		
 Body Insr	ection Comments	Note: som	e defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Minor Stone Chips Windscreen						Left front	4.5 mm		
						Right front	5.	.0	mm
						Left rear	3.5 mi		mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Oil Seepage & Underbody Surface Rust - Expected for Age & Mileage Rear Suspension Not Stock - Minimal Travel						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Rear Benc	h Torn, Drivers Se	at Worn			Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Spare Wheel Need Replacing						Window winder RR	<		
						Rear view mirrors	~		
						Radio (basic test only)	<		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Samuel Weir Date: 05 Dec 2024									
Inspected by: Samuel Weir Date: 05 Dec 2024									

I have read and understood this condition guide.

Name: