

Report ID: 26,447,777 5 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	QNE53	Reg Expiry:	08 Nov 2025	Engine	1 435	1 an	
WoF Expiry:	2013 06 Dec 2025	Odometer:	64,480 Kms	Good No:	26447777	Oil level			
VIN:	7AT0C13JX23105834	Next Service:	-	Service Histor	-	Smoke & fumes	~		
	74100133723103834	Next Service.	74,479 KIIIS	Service mistor	<b>y.</b> NO	Performance	V		
Note: This re	port is not a warranty						~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Noise			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:			DP			Performance	~		
S = scratch						Radiator / Hoses (visual)			
D = dent						Transmission			
R = rust	MID			$1 \wedge$	HUY	Operation	~		
PT = paint def	ect M					Noise	~		
C = crack P = pin dent	III			· ·		Clutch			~
* = decals SC DD						CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs W P P W						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		1
					Tyres (lowest observed tread depth of tyres)				
						Left front	2.7	7	mm
						Right front	3.4	ł	mm
						Left rear	2.1		mm
Conditions During Body Inspection: Dry						Right rear	3.3	3	mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Caral					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Daabbaa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive:   Dry   Central locking							~		
						Remote locking	~		
	ming Mechanism:	Timing (				Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:   Reversing camera							~		
Inspecte	Inspected by: Hoani Saunders Date: 06 Dec 2024								

I have read and understood this condition guide.

Name: .....

Signature: .....