

Report ID: 26,449,104 3 Version: 12 Dec 2024 Created:

| Make: | Ford | Model: | Ranger | Body Style: | Utility | | Pass | Fail | N/A |
|--|------------------------|-----------------|------------------------|-----------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2020 | Registration: | NAD56 | Reg Expiry: | 19 Aug 2025 | Engine | | | |
| WoF Expiry: | 02 Sep 2025 | Odometer: | 140,113 Kms | Good No: | 26449104 | Oil level | ~ | | |
| VIN: | MPBUMFF50LX276264 | Next Service: | 150000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Parts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | S | -0 | SD SD | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent D = suct SSC D D D D D D D D D D D D D D D D D D | | | | | | Operation 🖌 | | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | |
| C = crack | | | | $+ \vee$ | D | Clutch | • | | ~ |
| P = pin dent | HIC | | | | 74 <u>11</u> | CV joints | ~ | | |
| * = decals SDSC 919 | | | | | | Wheel bearings | v | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SDR SDR SDR SDR | | | | | | Performance | ~ | | |
| Body Incr | | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | pection Comments | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| Tail lights/reversing camera /parking sensors need refit | | | | | | Left front 6.0 mm | | | mm |
| Dash warning stay on(passenger door opening warning) Odometer cluster cracked | | | | | | Right front | 6.0 mr | | mm |
| Roof dent | | | | | | Left rear | | | mm |
| Conditions During Body Inspection: Wet | | | | | Right rear | 5.0 mm | | mm | |
| | | | | | | Spare | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | Suspension | | | | |
| Four wheel drive | | | | | | Suspension performance | ~ | | |
| Underbody muddy | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | | ~ | |
| Carpets | Average | | | | | Indicators | | ~ | |
| Panels | Average | | | | | Dashboard warning lights | | ~ | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | | ~ | |
| | | | | | | Remote locking | | ~ | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | ~ | |
| Inspected by: Xinghui Lin Date: 09 Dec 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: