

Report ID: 26,449,561 5 Version: 12 Dec 2024 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2020	Registration:	NAD70	Reg Expiry:	10 Aug 2025	Engine	I	I	1
WoF Expiry:	17 Jul 2025	Odometer:	121,565 Kms	Good No:	26449561	Oil level	~		
VIN:	MNAUM2F50LW077219	Next Service:	133000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent						Operation	~		
R = rust PT = paint defect						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
*=decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs						Performance 🖌			
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments							-	oftyre	25)
Hole on deck steel under passenger seat						Tyres (lowest observed tread depth of tyres)			
Tail lights/reversing camera/parking sensors /number plate need refit						Right front	4.5 mm		-
Rear view mirror needs refit Jack missing						Left rear			mm mm
Conditions During Body Inspection: Wet						Right rear	4.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder bonnet inspection comments						Suspension			
Four wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior Comments						Operation	~		
						Electrical / Accessories		1	
Seats	Average					Head lights	~		<u> </u>
Carpets	Average					Tail lights		~	
						Indicators		~	<u> </u>
Panels	Average					Dashboard warning lights		~	
Dashboa	rd Good					Wipers (front & rear)	~		
	0000					Window winder FL	~		
Concert	ommerte					Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL			~
Dash warning stay on(passenger door opening warning)						Window winder RR			~
Car can not	be locked properly					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
			<u>.</u>			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	
Increasted by Xingbuil in									
Inspected by: Xinghui Lin Date: 05 Dec 2024									
I have read and understood this condition guide. Name:									