

Basic Vehicle Condition Guide

Report ID: 26,449,934


Version: 3

Created: 12 Dec 2024

Make: Model: Suzuki **Grand Vitara Body Style:** SUV Year: 2012 Registration: GNF964 Reg Expiry: 18 Mar 2025 **Odometer:** WoF Expiry: 30 Mar 2025 138,715 Kms **Good No:** 26449934 VIN: JSAJTAA4V00250158 Next Service: 149,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Rear window tint bubbles

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Radio screen has dead pixels. One remote nw

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 02 Dec 2024

Name:

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | ' |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 2.0 | | mm |
| Right front | 2.0 | | mm |
| Left rear | 2.0 | | mm |
| Right rear | 2.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | ı | 1 |
| Operation 🗸 | | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | 1 |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Signature: