

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

	full machanical increase	Cooling System						
6	i iuli mechanicai inspect	ion prior to purchase and this can be arranged for an additional charge.	Coolant condition	~				
Γ	SC SC		Performance	~				
L	(ey:		Radiator / Hoses (visual)	~				
S = scratch D = dent R = rust S SC			Transmission					
			Operation	~				
PT = paint defect		Noise	~					
L	= crack	Clutch			~			
P	= pin dent	CV joints	~					
L		Wheel bearings	~					
	C = stone chips / = significant scuffs	Brakes						
ľ	s significant scuris	W SDSC S W S	Performance	~				
	Body Inspection Co	Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~				
		Minor stone chips on windscreen			Tyres (lowest observed tread depth of tyres)			
			Left front	5	5.0	mm		
			Right front	5	5.5	mm		
			Left rear	3	5.0	mm		
Conditions During Body Inspection: Dry			Right rear	3.0		mm		
			Spare	Yes				
Under Carriage & Under Bonnet Inspection Comments			Suspension					
	All wheel drive		Suspension performance	~				
			Steering performance	~				
			Shock absorbers	~				
			Air Conditioning / Heater	1		1		
			Operation		~			
	Interior Comments		Electrical / Accessories					
	Seats	Good	Head lights	~				
		Good	Tail lights	~				
	Carpets		Indicators	~				
	Panels	Good	Dashboard warning lights	~				
		Good	Wipers (front & rear)	~				
	Dashboard		Window winder FL	~				
			Window winder FR	~				
General Comments			Window winder RL	~				
	A/C does not go compl	Window winder RR	~					
			Rear view mirrors	~				
			Radio (basic test only)	~				
			CD (basic test only)	~				
L			Number of keys	2	1	1		
Γ	Road Conditions Du	Central locking	~					
			Remote locking	~				
	Engine Timing Mec	hanism: Timing Chain	Sat. Nav. (basic test only)	~				
Evidence of Cam Belt Replacement: Not Applicable Kms:			Reversing camera	~				
	lange i 11 - 1 -				•			
	Inspected by: Javk	ID COUIDS	Date: 28 Nov 20	24				

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,452,177 Version: 2 05 Dec 2024 Created:

Pass

V

V

V

V

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A