

Report ID: 26,452,363 Version: 2 05 Dec 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A	
Year:	2013	Registration:	QYN119	Reg Expiry:	21 Dec 2024	Engine				
WoF Expiry:		Odometer:	215,367 Kms	Good No:	26452363	Oil level	~			
VIN:	MMU148LK0EH60554			Service Histor		Smoke & fumes	~			
			223000			Performance	~			
	port is not a warranty					Noise	~			
	a guide only. Conside sting undertaken. The					Cooling System	v			
	ical inspection prior to					Coolant condition	~			
						Performance				
Key:		-0	S SC S			Radiator / Hoses (visual)	マ マ			
S = scratch						Transmission				
D = dent	sc all				HID P					
R = rust				10		Operation	~			
PT = paint def	ect	- 1		$\square \cup$		Noise	~			
C = crack P = pin dent	Ho					Clutch			~	
* = decals	dic				Ella	CV joints	~			
SC = stone chips						Wheel bearings	~			
W = significant scuffs						Brakes				
					S	Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
Minor stone chips on windscreen						Tyres (lowest observed tread depth of tyres)				
						Left front 2.0			mm	
						Right front	3.	.0	mm	
						Left rear	3.	.0	mm	
Conditions During Body Inspection: Dry						Right rear	2.	.5	mm	
						Spare	e Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rear wheel	drive					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
						Operation	~			
Interior Comments						Electrical / Accessories			1	
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	0000					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Card					Wipers (front & rear)	~		-	
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
Freshly Serviced						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		~	
		D.:				Central locking	2			
Road Con	ditions During Test	Drive:	Dry				v			
Engine Timing Mechanism: Cambelt						Remote locking	~			
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~	
LUNCINCE				1.11 . .		Reversing camera	~			
Inspected by: Jaykib Collins Date: 28 Nov 2024										
						- -				
I have read	and understood th	is condition o	juide. Name:			Signature:				