

Basic Vehicle Condition Guide

Report ID: 26,452,901


Version: 4

Created: 12 Dec 2024

Make: Model: Subaru Impreza **Body Style:** Hatchback Year: 2014 Registration: QAE779 Reg Expiry: 28 Dec 2024 WoF Expiry: **Odometer:** 01 Jul 2025 138,024 Kms **Good No:** 26452901 VIN: 7AT0GF09X23070045 Next Service: 140447 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

No underbody inspection

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Sara Haggerty

Create	d: 12	2 Dec 2	024
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	Į.		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	<u> </u>		
Performance	V		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	L
Left front			mm
Right front	5.0 5.0		mm
Left rear	5.0		mm
Right rear			mm
Spare		N/A	
Suspension		,,,,	
Suspension performance	V		
Steering performance	·		
Shock absorbers	· ·		
Air Conditioning / Heater			
Operation	·/		
Electrical / Accessories			
Head lights	•		
Tail lights	•		
Indicators	<i>y</i>		
Dashboard warning lights	•		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	<i>v</i>		
Window winder RR			
Rear view mirrors	V		
	•		
Radio (basic test only)			.,
CD (basic test only)	2		<i>'</i>
Number of keys	2		<u> </u>
Central locking	•		
Dama ata Ingeletera	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Remote locking			1 4
Remote locking Sat. Nav. (basic test only) Reversing camera	V		~

I have read and understood this condition guide.

Name:

Signature: