

I have read and understood this condition guide.

Report ID: 26,453,224 4 Version: 12 Dec 2024 Created:

Signature:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	Registration:	LML812	Reg Expiry:	18 Jul 2025	Engine	1		L
WoF Expiry:	23 Jul 2025	Odometer:	102,073 Kms	Good No:	26453224	Oil level	~		
VIN:	WVWZZZAUZJW257304	Next Service:	115219	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			P SC S		SC	Performance	~		
Key:		=				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S SC			710	SC W	Operation	~		
PT = paint defe	ect NP			$\left(\left \left(\right) \right\rangle \right)$	70111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dle				74116	CV joints	~		
* = decals				10	S SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = signincan	SC W		SC		S D	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
					Left front	4.	.0	mm	
						Right front	3.0 mi		mm
						Left rear	4.	.3	mm
Conditions During Body Inspection: Wet						Right rear	4.8 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	•		
No underbo	ody inspection					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	marks					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	scratches					Dashboard warning lights	2		
Dashboa	rd c					Wipers (front & rear)	۲		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking									
Remote lockin							~		
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Melissa Wilson Date: 09 Dec 2024									
Inspected by, Incluse mison Date: 07 Dec 2024									

Name: