

| Make: | Ford | Model: | Ranger | Body Style: | Utility | 1[| | Pass | Fail | N/A | |
|--|-------------------|----------------------|------------------------|--------------------|-----------------------|----|--|--------|--------|----------|--|
| Year: | 2020 | Registration: | NDG487 | Reg Expiry: | 09 May 2025 | l | Engine | | | | |
| WoF Expiry: | 18 Nov 2025 | Odometer: | 195,198 Kms | Good No: | 26453662 | lŀ | Oil level | ~ | | | |
| VIN: | MPBUMFF50LX296147 | Next Service: | 201000 | Service Histor | y: Yes | lŀ | Smoke & fumes | ~ | | | |
| | | | | | | il | Performance | ~ | | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | lŀ | Noise | ~ | | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | lt | Cooling System | | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | lŀ | Coolant condition | ~ | | | |
| | | | | | | ۱ŀ | Performance | ~ | | | |
| Key: | | -0 | | -01- | | lŀ | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | ļŀ | Transmission | | | | |
| D = dent R= ruft SC D D S | | | | | | lŀ | Operation | ~ | | | |
| R = rust PT = paint defect | | | | | | lŀ | Noise | ~ | | | |
| C = crack | | | | + | SC SC | ŀ | Clutch | • | | ~ | |
| P = pin dent | | | | | | | CV joints | ~ | | | |
| *= decals DSC 000 SD | | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | lŀ | Brakes | | | | |
| W = significant scuffs | | | | | | ļŀ | Performance | ~ | | | |
| | | Note: son | ne defects & blemishes | may not be disr | blaved in the diagram | lŀ | Hand Brake | v v | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | ļŀ | | - | oftyre | | |
| Stone chips on front windscreen | | | | | | lŀ | Tyres (lowest observed tread depth of tyres) Left front 5.0 mm | | | | |
| | | | | | | lŀ | Right front | | | mm mm | |
| | | | | | | lŀ | Left rear | | | | |
| | | | | | | iŀ | | | | mm | |
| Conditions During Body Inspection: Wet | | | | | | ┨┝ | 5 | | | mm | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | 1 | Spare Yes | | | | |
| and canage a onder bonnet inspection comments | | | | | | ļŀ | Suspension | | | | |
| Four wheel drive | | | | | | ╟ | Suspension performance | ~ | | | |
| engine oil leaks Underbody muddy | | | | | | ╟ | Steering performance | ~ | | | |
| | | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | Air Conditioning / Heater | | | | |
| Interior Comments | | | | | | 1 | Operation 🖌 | | | | |
| | | | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | | Head lights | ~ | | | |
| Carpets | Good | | | | | | Tail lights | ~ | | | |
| | | | | | | | Indicators | ~ | | | |
| Panels | Average | | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | rd Average | | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | ┨┞ | Window winder FL | ~ | | | |
| Concret | | | | | | ٦ŀ | Window winder FR | ~ | | | |
| <u>General Comments</u> | | | | | | | Window winder RL | ~ | | | |
| Brake noisy | | | | | | | Window winder RR | ~ | | | |
| | | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | ļ | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Wet | | | | | | | Central locking | ~ | | | |
| Engine Timing Mechanicmy Timing Chain | | | | | | il | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | [[| Sat. Nav. (basic test only) | | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | | Reversing camera | ~ | | | |
| Inspected by: Xinghui Lin Date: 04 Dec 2024 | | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: