

Basic Vehicle Condition Guide

Report ID: 26,454,010


Version: 2

Created: 06 Dec 2024

Make: Model: Hyundai Kona **Body Style:** SUV Year: 2021 Registration: NUW272 Reg Expiry: 28 Apr 2025 WoF Expiry: **Odometer: Good No:** 17 Oct 2025 77,143 Kms 26454010 VIN: KMHK281GUMU14056 Next Service: 90,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Fwd

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Good | | |
| Carpets | Average | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Service light on,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

28 Nov 2024 Inspected by: Marlon Espena

| | Pass | Fail | N/A | |
|------------------------------|----------|---------|-----|--|
| Engine | | | | |
| Oil level | | | ~ | |
| Smoke & fumes | ~ | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 6 | .0 | mm | |
| Right front | 6 | .0 | mm | |
| Left rear | 7 | .0 | mm | |
| Right rear | 7.0 | | mm | |
| Spare | | N/A | | |
| Suspension | • | | | |
| Suspension performance | ~ | | | |
| Steering performance | V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | v | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | <i>'</i> | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature: